



Aluminum Coil Over Bump Stop
 6025A-70
 w/2.5" Spring Plates
 OR
 6030A-70
 w/3.0" Spring Plates
 OR
 6050A-70
 w/5.0" Spring Plates

04/13/2010

6025A-70

Item ID	Item Description	Qty Needed
2812	½" Male Rod End	2.00
2843	½" Hardened Flat Washer	1.00
2846	2.5" Spring Plate Adapter	1.00
2848-A	Adjuster Nut, Aluminum	1.00
2851-A	Cap, Aluminum	1.00
2859	2.5" Slotted Spring Plate	1.00
2863-A	Threaded Body, Aluminum	1.00
2864	1/4-20 x 3/16 Plug	1.00
2873-7	7" Stroke Shaft, 9 5/8" L	1.00
2874	¼ -20x5/16 Nylon Tip Lock Screw	1.00

Item ID	Item Description	Qty Needed
2878	.25-20x3/8 BHSCS	2.00
4507	Shaft Bushing	2.00
4508	Shaft Wiper	2.00
4511-A	Washer	3.00
4520	.50-20 x 1 Gr5 HCS	2.00
4521	.44 Mega Thick Flat Washer	1.00
4531	Grease Fitting	1.00
4558	1/2-20 RH Jam Nut	2.00
4563Y	Yellow Bump Stop	2.00
6061	Bushing Housing	1.00

4/20/2010

Parts that change for different models:

6030A-70

Item ID	Item Description	Qty Needed
INSTEAD OF 2846 & 2859		
3063	3.0" Slotted Spring Plate	1.00
3081	3.0" Spring Plate Adapter	1.00

6050A-70

Item ID	Item Description	Qty Needed
3093	5.0" Spring Plate	2.00

Optional Parts

Item ID	Item Description	Qty Needed
2812CM	Optional -Chrome Moly Rod End	1.00
2851-H	Optional- Cap w/Extended Rod End Mounting, Boss, Steel	1.00